

August 20, 2009

Release Note

updated: August 20, 2009

DVR Viewer2, JPEG2000 and ActiveX Plug-in software Version 2.1.5

1) Improved it might failed to download when download takes long time.

Applicable models:

- a) DSR-5716P/5709P
- b) DSR-3716/3716P
- c) DSR-3709/3709P
- d) DSR-3706/3706P
- e) DSR-5016/5016P/5009P –

2) Improved it might be unable to download through network on Windows Vista.

Applicable models:

- a) DSR-5716P/5709P
- b) DSR-3716/3716P
- c) DSR-3709/3709P
- d) DSR-3706/3706P